











XLR Cable Connector

NC*FXX & NC*MXX





Assembly Instructions

- (A)** Slide the boot onto the cable.
- (B)** Prepare cable as shown.
- (C)** Insert wires into the terminals and solder them.
- (D)** Put chuck onto the cable.
Attention: Pay attention to the guiding key.
- (E)** Slide insert and chuck together into the housing.
- (F)** Finish the installation by turning the bushing onto the connector.
- 
- 
- 
- 
- 
- 
- ORDER OF ASSEMBLY**

NC*FXX

			
bushing	chuck	insert	housing

NC*MXX

			
--------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------

NEUTRIK AG
Liechtenstein
Tel.: +423/237 24 24
Fax: +423/232 53 93
www.neutrik.com

NEUTRIK Zürich AG
Switzerland
Tel.: +41 1/736 5010
Fax: +41 1/736 5011

NEUTRIK (UK) Ltd.
Great Britain
Tel.: +44 1983/811 441
Fax: +44 1983/811 439

NEUTRIK USA INC.
USA
Tel.: +1 732/901 9488
Fax: +1 732/901 9608

NEUTRIK Tokyo Ltd.
Japan
Tel.: +81 3/3663 4733
Fax: +81 3/3663 4796

NEUTRIK France
France
Tel.: +33 1/4131 6750
Fax: +33 1/4131 0511

NEUTRIK Vertriebs GmbH
Germany / Netherlands
Tel.: +49 8131/28 08 90
Fax: +49 8131/28 08-30

Draft. Nr.: BDA 158 / 3102M1381
Update: 14.02. 2005



NEUTRIK
CONNECTING THE WORLD

Data subject to change without prior notice. ©2005 NEUTRIK®. ALL RIGHTS RESERVED.