


Ruggedized RJ45 Data Connector Cabel Connector with X Series bushing - NE8MC-1

Assembly Instructions



- (A)** Slide the bushing over the cable.
- (B)** Assembly the RJ45 plug on the cabel.
- (C)** Put chuck onto the cable.
- (D)** It applicable press the adapter into the port.
- (E)** Position the ring on the cable end (flush to the face).
In combination with (D) the position ring (E) can but must note used depending to the design of the RJ45 plug.
- (F)** Slide the connector into the housing.
pay attention: the connector latch has to point downwards (opposite direction of RJ45 lettering)
- (G)** Slide the chuck in the housing
(pay attention to the guiding key).
- (H)** Slide the boot to the housing and tighten the bushing.